

Vehicle History Report #: 53565175 Report Date: May 24, 2024 | 6:43 PM EDT

> Report Status: Complete Reference: 1094579

2013 RAM 2500 ST

Pickup | 8 Cylinders | Gas 3C6TR5CT9DG523399 Country of Assembly: Mexico Last Reported Odometer: n/a



No Accident/Damage Records Found



Last Registered In: Alberta (Normal)



0 Service Records Found



No U.S. History Found



5 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca

(i)

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 24, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of Alberta in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Open Recalls

Recall #: R23 | REPROGRAM OCCUPANT RESTRAINT CONTROL MODULE Recall Date: 2015 Aug 21

Recall Description

OCCUPANT RESTRAINT CONTROL (ORC) MODULE SOFTWARE MAY CONTAIN SIDE IMPACT CALIBRATIONS THAT ARE OVERLY SENSITIVE.

Remedy

THE ORC MODULE MUST BE REPROGRAMMED WITH NEW SOFTWARE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: R36 | STEERING WHEEL WIRING Recall Date: 2015 Sep 04

Recall Description

THE STEERING WHEEL WIRE HARNESS MAY BECOME CHAFFED BY THE DRIVER AIRBAG MODULE RETAINER SPRING ENDS.

Remedy

THE STEERING WHEEL WIRE HARNESS WILL BE INSPECTED, AND IF NEEDED REPAIRED. THE STEERING WHEEL WIRE HARNESS WILL BE REPOUTED AND SECURED TO PREVENT WIRE CHAFFING AND PROTECTIVE CAPS WILL BE INSTALLED ONTO THE AIRBAG RETAINER SPRING ENDS.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: T25 | OCCUPANT RESTRAINT CONTROL MODULE Recall Date: 2017 Jun 22

Recall Description

THE OCCUPANT RESTRAINT CONTROL MODULE MAY ACTIVATE A DIAGNOSTIC TROUBLE CODE (DTC) DUE TO EXTERNAL STIMULUS WHICH DISABLES ITS ABILITY TO SENSE VEHICLE ROLLOVER EVENTS. WHEN THE DTC IS SET, AIRBAG AND SEAT BELT PRETENSIONER DEPLOYMENT BASED ON ROLLOVER SENSING IS DISABLED FOR THE IGNITION CYCLE IN WHICH THE DTC WAS SET.

Remedy

THE ORC MODULE ON INVOLVED VEHICLES MUST BE REPROGRAMMED WITH NEW SOFTWARE,

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: T79 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Jan 04

Recall Description

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

Remedy

For 2013-2017 model year; Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated. For 2009-2012 model year; replace the BTSI, BCM software update not applicable.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.

Recall #: V44 | 2013-2018 D TRUCK TAILGATE LATCH Recall Date: 2019 May 16

Recall Description

The tailgate actuator limiter tab within the power lock actuator control assembly may fracture allowing the lock rod control bracket to overtravel which may pull the lock rods and release the latches, potentially resulting in the tailgate inadvertently falling open at any time.

Remedy

FCA US will conduct a Voluntary Safety Recall on all affected vehicles. The remedy for this item will limit the locking actuator travel and not allow the pivot arm from overtraveling and pulling on the locking/unlocking rods

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit Ram's website.



Stolen Vehicle Check



DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Oct 4		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2014 Dec 29	900000 1931 1930 1930 1930 1930 1930 193	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2015 Aug 21	valuar (arcio) (arcio) and (arcio) (a	RAM	Recall	Manufacturer Recall Issued Recall # R23
2015 Sep 4	ntikak dara salma denartira denarra arrawana samar encurra encurra encurra encurra encurra encurra encurra encu	RAM	Recall	Manufacturer Recall Issued Recall # R36
2015 Dec 11	ante de concentrativa constanta de constanta que super-constant constanta con que es que es que esque	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2016 Dec 12	Ambiel fact to a congress could be stored to committee of consist a term of a money of	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2017 Jun 22		RAM	Recall	Manufacturer Recall Issued Recall # T25
2017 Dec 18	тетвански выполня на почения выполн	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2018 Jan 4	19 - 19 - 19 - 19 - 19 - 19 - 19 - 19 -	RAM	Recall	Manufacturer Recall Issued Recall # T79
2018 Dec 10	3010-31 3931 193 1933 193 193 193 193 193 193	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2019 May 16	MICCOCACACOCACO CONTRA ECONOCIO ARCESES ECONOCIO ACCESES ECONOCIO ECONOCIO ECONOCIO ECONOCIO ECONOCIO ECONOCIO	RAM	Recall	Manufacturer Recall Issued Recall # V44
2019 Dec 11	scenationement communication and an emission of the second section of the second section of the second section	Motor Vehicle Dept, Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2020 Dec 3	175-174-1 1 10-21 1 2011/42) 2 2013 1 2013 1 2014 1 2014 1 2014 1 2014 1 2014 1 2014 1 2014 1 2014 1 2014 1 2014	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2021 Dec 31	destinations de commence d	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2022 Dec 22	ranceantendeplaceantendeplaceante, pipigipi mese imberiori, din minimi primpi pripaga propria	Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white



This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source deta providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, commeter readings or other information where discrepandes that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports or omissions. The reports or any information and its source data providers from external sources and its source data providers from external sources, express or implied, including any warranties of timeliness, accuracy, merchantability, merch

© 2024 CARFAX Canada ULC, All rights reserved.

